

EPA REGION 10 RISK MANAGEMENT PROGRAM 1 DAY Training

Tuesday June 10, 2014

TIME: 9 am – 5 pm



Portland, Oregon

Portland GSA Federal Building - Auditorium
911 NE 11th Avenue
Portland, OR 97232-4128

**The Environmental Protection Agency (EPA) Region 10 RMP team is offering a
FREE RISK Management Program Training.**

EPA Region 10 will provide information about how to comply with RMP reporting and emergency planning requirements. The instructors: EPA RMP Inspectors with experience in RMP inspections, enforcement, emergency management and compliance.

Who should attend?

Safety Managers and Process Safety, Operations and Plant Managers; Engineering and Maintenance Managers; RMP and PSM Coordinators, Supervisors, Operators and Maintenance Technicians; and Technical, Safety and Environmental Health and other Safety/Industry Professionals interested in learning more about the Risk Management Program

Major components of the RMP training:

General review of RMP elements, common inspection deficiencies and tips on using RMP*eSubmit and other tools for on-line updates/corrections to your RMP

Register: To confirm participation and guarantee a space please send the following information:

- Name and email of person attending (limit 2 per facility)
- Company and or/Facility Name and Address
- Phone Contact including office phone and/or cell phone

Email registration information to: garcia.terry@epa.gov

TRAINING LOCATION: 911 Federal Building –Auditorium, 911 NE 11th Ave, Portland, Oregon 97232. If you have questions, please call 503-974-6204

FOOD: There is a cafeteria on site with food available for purchase.

SECURITY: When entering the Federal Building, attendees will need to present a photo ID (i.e. driver's license) and pass through a Magnetometer X-RAY (similar to Airport Security Technology). Any items (i.e. bags, backpacks, etc.) you bring will be x-rayed and subject to search.

Parking: Public parking available in lots near the site. Transit: MAX Lloyd Center

Contact: Terry Garcia, EPA Region 10 EPA, RMP Specialist at 206-553-1761 for information on training.

EPA Region 10's RMP website:

<http://yosemite.epa.gov/r10/airpage.nsf/enforcement/rmp>