



WISCONSIN
DEPARTMENT OF
AGRICULTURE,
TRADE AND
CONSUMER
PROTECTION

OFFICE LOCATION

2811 Agriculture Drive
Madison, WI 53708-8911

1-800-422-7128
608-224-4960

News

Nov. 2014 Edition

Dear Wisconsin Children's Safety Advocates:

In October 2014, the U.S. Consumer Product Safety Commission issued a total of **4 recalls relating to products affecting children**. Attached is a summary of the releases identifying the product, the problem, and what should be done with the recalled product.

We have found that not all of the recalls are picked up by the news media as they occur. This monthly summary will give you the opportunity to review all of the children's product safety recalls for the past month. If you are interested in a complete text of the recall, double click on the hyperlink at the end of the recall description. This will direct you to the recall notice located on the CPSC website.

- **Toys R Us Recalls Toy Toaster Sets Due to Choking Hazard**
[\(15-007\)](#)
- **Toys R Us Recalls Children's Sandals Due to Choking Hazard**
[\(15-002\)](#)
- **Meijer Recalls Halloween Projector Flashlight Due to Burn Hazard** [\(15-011\)](#)
- **Cane Creek Recalls Bicycle Shocks Due to Risk of Injury**
[\(15-013\)](#)

If you would like to sign up for the Keep Your Kids Safe newsletter, please subscribe at

https://public.govdelivery.com/accounts/WIDATCP/subscriber/new?topic_id=WIDATCP_161 or contact Bobbi Erb at (608) 224-4955 or bobbi.erb@wisconsin.gov.

If you have any questions or want to file a complaint regarding an unsafe product, contact:

Wisconsin Department of Agriculture, Trade and Consumer Protection
Bureau of Consumer Protection
2811 Agriculture Drive
Madison, WI 53708

KEEP YOUR KIDS SAFE

Release Number: (#15-007) Toys R Us, of Wayne, N.J., is announcing the voluntary recall of about 30,000 in the U.S. and about 6,000 in Canada Just Like Home brand toy toaster sets. The teal blue plastic toy toaster has silver trim around the slice opening on top, with an orange slider handle on the side and orange 3-dimensional adjustment knob outlined with orange dots in a half moon shape on the face of the toaster in the left bottom corner. "Just like home" is printed in white on the front right bottom corner of the toaster. The toaster measures about 4 inches in height by 5-1/2 inches in length by 2 inches in width. The toaster set was sold with two plastic toast slices and two plastic half bagel slice accessories. Model number 5F60589 is printed on a white label on the bottom of the toaster and above the UPC bar code in the lower right hand corner of the product packaging.

Problem: The plastic toast, under pressure, can crack and break into small pieces creating sharp edges and posing a choking hazard.

What to do: Consumers should immediately take this product away from children and return it to any Toys R Us to receive a full refund. You can contact Toys R Us at (800) 869-7787 anytime or online at www.toysrus.com and click on Safety for more information.



<http://www.cpsc.gov/en/Recalls/2015/Toys-R-Us-Recalls-Toy-Toaster-Sets/>

Release Number: (#15-002) Toys R Us Inc., of Wayne, N.J., has announced the voluntary recall of about 19,000 Koala Baby girl's plastic sandals with butterfly wings attached to the toes with rhinestones and hard or soft cork-type soles. Sandal colors include white or combination pink, gold and blue. They were sold in baby sizes 0 to 3 and girl's sizes 2 to 10. "Koala Baby" and the size are printed on the soles. White soft-soled sandals have model number GNL 43633BR and item number 795267 printed on a tag sewn into the sandal's ankle strap. White hard-soled sandals have model number GNL 43706BR and item number 795313. Combination pink, gold and blue soft-soled sandals have model number GNL 43634BR and item number 795275. Combination pink, gold and blue hard-soled sandals have GNM 41761BR and item number 845795.

Problem: The butterfly wings on the children's sandals can rip and detach, posing a choking hazard to young children.

What to do: Consumers should immediately take the recalled sandals away from young children and return the sandals to any Toys R Us or Babies R Us for a full refund. You can contact Toys R Us at (800) 869-7787 anytime or online at www.toysrus.com and click on Safety for more information.



<http://www.cpsc.gov/en/Recalls/2015/Toys-R-Us-Recalls-Childrens-Sandals/>

Release Number: (#15-011) Meijer Distribution Inc., of Grand Rapids, M.I., announces the voluntary recalls about 8,600 Signature Designs

Halloween image projector. The projector is a flashlight with cap that holds special lenses to project messages and images onto a wall or other surfaces. The flashlight handle is black with the word Halloween and pictures of a skull and a jack o' lantern printed in white. The handle is about 7 inches long and holds two size C batteries. The cap is orange and is about 3 inches high and about 2 inches in diameter. The projector comes with three lenses: an orange lens with a black jack o' lantern, a yellow lens with a black bat and a purple lens with the words "Trick or Treat" in black. A clear label with "Signature Designs (HK) Ltd, Ningbo, China, 14-121-02, 05/2014" printed in white is on the side of the handle opposite the orange on/off switch.

Problem: The flashlight can overheat and melt the plastic handle, posing a burn risk to the user.

What to do: Consumers should immediately stop using the flashlight, remove the batteries and return it to the customer service desk at any Meijer store or contact Meijer for a full refund. You can contact Meijer at (800) 927-8699 anytime or online at www.meijer.com and click on Product Recalls at the bottom of the page for more information.



<http://www.cpsc.gov/en/Recalls/2015/Meijer-Recalls-Halloween-Projector-Flashlight/>

Release Number: (#15-013) Cane Creek Cycling Components, Inc.; Fletcher, N.C., is announcing the voluntary recall of about 5,000 in the US and 500 in Canada Cane Creek Cycling Components DBINLINE bicycle rear shock absorbers. The shocks are marked with graphics that incorrectly identify the adjustment directions for High Speed Rebound (HSR) damping. HSR on the shock is decreased by turning the adjuster counter-clockwise and increased by turning it clockwise. The incorrect graphics present the opposite; that is, the plus(+) and minus(-) symbols are switched. The consumer can be misled or confused when adjusting HSR on these shocks. The shocks come in black anodized aluminum with the words "**INLINE**"

marked on the air can portion of the shock and are attached to a full-suspension mountain bike frame. Recalled products have a serial number on the underside of the top valve body in the following ranges: AA00002 – AA07304 and SA00077 – SA03926.

Problem: The shock absorber is marked with graphics that incorrectly identify the adjustment directions for High Speed Rebound (HSR) damping. Following these directions will cause unexpected behavior by a bike's suspension and pose a fall hazard to a rider.

What to do: Consumers should immediately stop using the product and contact Cane Creek for a repair decal kit to correct the HSR adjustment markings on affected product. You can contact Cane Creek Cycling Components at (800) 490-3663 from 9 a.m. to 5 p.m. ET Monday through Friday, or online at www.canecreek.com and click on "Safety and Recall" for recall information.



<http://www.cpsc.gov/en/Recalls/2015/Cane-Creek-Recalls-Bicycle-Shocks/>