

Issued Between 5/12/2017 and 5/18/2017

Total Permits : 8

Valuation is Greater than or Equal to \$50,000

Address	Issue Date	Permit Number	State Valuation
301 SUMMIT AVE	05/16/2017	B 17 037844 RPR	\$117,059.00

District Council: 8 **Interior/Exterior?** Exterior Only

Work Type : Repair

Permit Status: Active/Issued

Contractor : Les Jones Roofing Inc
941 W 80th St
Bloomington MN 55420-0000
952-881-2241

Owner : Germanic-american Institute
301 Summit Ave
St Paul MN 55102-2118
651-222-7027

Conditions:

SEE LETTER IN THE DOCUMENT TAB, FOR THE BASEMENT FIRE SEPARATION AGREEMENT UNDER PERMIT #09-095680. *Roof Repair: Contact the designated Building Inspector between 7:30-9:00am (M-F), with the proposed schedule and scope of work details, before work commences.

Address	Issue Date	Permit Number	State Valuation
76 KELLOGG BLVD W	05/15/2017	B 16 086104 REM	\$250,000.00

District Council: 9 **Interior/Exterior?** Interior Only

Work Type : Remodel

Permit Status: Active/Issued

Contractor : Reiling Construction Co Inc
867 Pierce Butler Rte
St Paul MN 55104-0000
651-690-2366

Owner : District Heating Devel Co
76 Kellogg Blvd W
St Paul MN 55102-1611
651-297-8955

Conditions:

Address	Issue Date	Permit Number	State Valuation
1516 BREWSTER ST	05/12/2017	B 17 012732 NEW	\$829,420.00

District Council: 10

Interior/Exterior?

Work Type : New

Permit Status: Active/Issued

Contractor : Rjm Construction
701 Washington Ave N Ste 600
Minneapolis MN 55401
952-837-8613

Owner : Hmong Education Reform Company
1515 Brewster St
Saint Paul MN 55108-2612
651-209-8002

Conditions:

EROSION & SEDIMENT CONTROL INSPECTION REQUIRED ALL EROSION AND SEDIMENT CONTROL DEVICES SHALL BE INSTALLED PER APPROVED SITE PLAN AND SHALL BE INSPECTED AND APPROVED BY THE INSPECTOR PRIOR TO BEGINNING EXCAVATION. CONTROL DEVICES SHALL BE MAINTAINED UNTIL FINAL APPROVAL OF THE PROJECT.
Structural Review - 5/12/17 BK - Approval of permit for foundation and typical construction work only. Installation of dome shall be done under different permit and permit required for re-installation on an annual basis. *This Project must meet the Lighting Power Budget requirements of the Mn. State Energy Code.

Issued Between 5/12/2017 and 5/18/2017

Total Permits : 8

Valuation is Greater than or Equal to \$50,000

Address	Issue Date	Permit Number	State Valuation
1544 BREWSTER ST	05/12/2017	B 17 012730 NEW	\$4,334,921.00

District Council: 10

Interior/Exterior?

Work Type : New

Permit Status: Active/Issued

Contractor : Rjm Construction
701 Washington Ave N Ste 600
Minneapolis MN 55401
952-837-8613

Owner : Hmong Education Reform Company
1515 Brewster St
Saint Paul MN 55108-2612
651-209-8002

Conditions:

EROSION & SEDIMENT CONTROL INSPECTION REQUIRED ALL EROSION AND SEDIMENT CONTROL DEVICES SHALL BE INSTALLED PER APPROVED SITE PLAN AND SHALL BE INSPECTED AND APPROVED BY THE INSPECTOR PRIOR TO BEGINNING EXCAVATION. CONTROL DEVICES SHALL BE MAINTAINED UNTIL FINAL APPROVAL OF THE PROJECT. *This Project must meet the Lighting Power Budget requirements of the Mn. State Energy Code.

Address	Issue Date	Permit Number	State Valuation
931 VANDALIA ST	05/18/2017	B 17 040701 EXP	\$71,698.00

District Council: 12

Interior/Exterior?

Work Type : Express Repair

Permit Status: Active/Issued

Contractor : John A Dalsin And Son, Inc.
2830 20th Ave S
Minneapolis MN 55407-0000
612-729-9334

Owner : Capp Industries Inc
7951 12th Ave South
Bloomington MN 55425-1017
952-854-6608

Conditions:

*ReRoof Flat/TearOff--No Structural Changes. Any roof drains, RTU Condensate lines, or similar which drain to the sanitary sewer must be disconnected and either drained to the storm sewer or to an approved location at grade. Commercial Roofs and Multi-Family Residential roofs on building more than 3-stories must be re-insulated to at least R-22.2 overall. All other residential buildings must be re-insulated to R-38 except that Multi-Family buildings may be insulated to R-30 when approved by this Office due to unusual existing conditions or difficulties. Roofing materials must be installed according to the manufacturer's specifications. Contact the designated Building Inspector between 7:30-9:00am (M-F), with your proposed schedule, before beginning work & CALL FOR INSPECTIONS as required.

Address	Issue Date	Permit Number	State Valuation
1910 GRAHAM AVE	05/12/2017	B 17 024305 REM	\$600,000.00

District Council: 15

Interior/Exterior? Interior Only

Work Type : Remodel

Permit Status: Active/Issued

Contractor : Engelsma Construction Inc
7119 31st Ave N
Golden Valley MN 55427

Owner : River Road li Investments Llc
9 7th Place W
Saint Paul MN 55102-1145
951-225-1913

Conditions:

Issued Between 5/12/2017 and 5/18/2017

Total Permits : 8

Valuation is Greater than or Equal to \$50,000

Address	Issue Date	Permit Number	State Valuation
600 ROBERT ST N	05/15/2017	B 17 038838 REM	\$105,000.00

District Council: 17 **Interior/Exterior?** Interior Only

Work Type : Remodel

Permit Status: Active/Issued

Contractor : Reiling Construction Co Inc
867 Pierce Butler Rte
St Paul MN 55104-0000
651-690-2366

Owner : State Of Minnesota
50 Sherburne Ave Rm G10
St Paul MN 55155-1495
651-201-2348

Conditions:

FINISHES

Address	Issue Date	Permit Number	State Valuation
401 SIBLEY ST	05/18/2017	B 17 028200 RPR	\$550,000.00

District Council: 17 **Interior/Exterior?** Exterior Only

Work Type : Repair

Permit Status: Active/Issued

Contractor : Restoration Systems Inc
1605 Audubon Road
Chaska MN 55318
952-368-0463

Owner : Bigos Mears Park Llc/Glaser Financial Group
8325 Wayzata Blvd Ste 200
Golden Valley MN 55426-1460
763-367-7421

Conditions:

comment
HPC

Repairing the Mears Park Place Apartments interior courtyard plaza and sidewalk. Separate permit and HPC approval required for 2018 perimeter repairs. Contractor will provide signed special inspections form on site for inspector.
SEE ATTACHED FOR PROJECT MANUAL

Grand Total Valuation: \$6,858,098.00