


INSTALLATION OPERATIONS STORYBOARD (23 FEB – 03 MAY 2019):

**Echoscope image of oil and gas plumes coming up from erosional pit next to
downed jacket at MC20 Site**



Vessel arrives on scene and launches ROV into water at MC20 site




Overboarding of the separator into the water at the MC20 site (25 March 2019)




Overboarding the porch into the water at the MC20 site (02 April 2019)



Echoscope image of porch installed with plumes coming through without the containment device installed



Echoscope image of containment system fully installed – no plumes coming from the erosional pit



Oil collected from site subsea

